Notice



☐ CORRECTION ● PRODUCTION CH ☐ SERVICE FLASH ☐ ADD INFORMATION	(
Please add this notice to the Service Ma	nual listed below.				
Category: COLOR TELEVISION	Date: OCTOBER / 22 / 2012				
Model: DP32642	Effective from : Chassis No. P32642-02				
Destination: U.S.A. / CANADA REF : No. SM780198-02					
Manual. If the Service Manual Chass	's back cover with the Chassis No. in the Service sis No. does not match the unit's, additional Service s is similar to Chassis No. P32642-00. Only the				

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

difference Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P32642-00 used in

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Model DP32642 (SM780198).

Item No. 088 OP2 Data should be changed from 0Dh to 0Eh in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

A: Misprint B: Quality Reliability C: Standardization

D: Design E: Add as a possible sub F: Schematic location change

G: Purchasing Request

2012
Corporation
Sanyo Manufacturing Corporation 2012
© Sanyo

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchange- ability	Reason
Page 18, Chassis Electrical Parts List	▲ A100	Old	1LG0B10Y10300	ASSY,PWB,ANALOG-COMP-Z6TE	1	NO	D
		New	1LG0B10Y103A0	ASSY,PWB,ANALOG-COMP-Z6TG	1	NO	
	▲ A200	Old	1LG0B10Y10900	ASSY,PWB,DIGITAL_Z-Z6TE	1	NO	D
		New	1LG0B10Y109A0	ASSY,PWB,DIGITAL_Z-Z6TG	1	NO	
	▲ EL901	Old	1AV4T40C30500	LCD(V315B6-L04)	1	NO	D
		New	1AV4T40C33600	LCD(T320XVN02.0)	1	NO	
	▲ U901	Old	N0AB2EF00004	UNIT,POWER-N8LA	1	NO	D
		New	N0AB3EJ00003	UNIT,POWER-Z6TG	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation P.O. Box 2000 3333 Sanyo Road Forrest City, Arkansas 72335-2000

October, 2012 SMC